



TITLE: LOW PROFILE CONTACT ASSEMBLY
INVENTOR: F. Morana, et al.
S.N.: 10/624,799
DOCKET: 18034 (AT #20958-02110)
ATTORNEY: Bruce Atkins; PHONE: (314)821-5070

1/6




FIG. 1



TITLE: LOW PROFILE CONTACT ASSEMBLY
INVENTOR: F. Morana, et al.
S.N.: 10/624,798
DOCKET: 18034 (AT #20956-02110)
ATTORNEY: Bruce Atkins; PHONE: (314)621-5070

2/6




FIG. 2



TITLE: LOW PROFILE CONTACT ASSEMBLY
INVENTOR: F. Morana, et al.
S.N.: 10/624,799
DOCKET: 18034 (AT #20958-02110)
ATTORNEY: Bruce Atkins; PHONE: (314)621-5070
REPLACEMENT SHEET

3/6




FIG. 3



TITLE: LOW PROFILE CONTACT ASSEMBLY
INVENTOR: F. Morana, et al.
S.N.: 10/624,799
DOCKET: 18034 (AT #20958-02110)
ATTORNEY: Bruce Atkins; PHONE: (314)821-5070

4/6




FIG. 4



TITLE: LOW PROFILE CONTACT ASSEMBLY
INVENTOR: F. Morana, et al.
S.N.: 10/624,799
DOCKET: 18034 (AT #20958-02110)
ATTORNEY: Bruce Atkins; PHONE: (314)621-5070
REPLACEMENT SHEET

5/6




FIG. 5

TITLE: LOW PROFILE CONTACT ASSEMBLY
INVENTOR: F. Morana, et al.
S.N.: 10/824,799
DOCKET: 18034 (AT #20958-02110)
ATTORNEY: Bruce Atkins; PHONE: (314)621-5070



6/6




FIG. 6